


Glasurit® Aerosol Silicone and Tar Remover



- General:** 541-5 is used to clean:
- The substrate before the application of 2K Primer Surfacer.
 - After finish sanding of the primers.
 - Cleaning agent for 22-, 55-, 90-Line systems.

Process: Clean areas with lint free cloth and 541-5, then wipe dry with a lint free cloth.

	Application	Aerosol Silicone and Tar Remover
	Paint System	22-, 55-, 90-Line
	VOC ready for use	6.5 lbs/gal; 779 gms/litre

Materials described are for application by professional trained personnel only using proper equipment. Products may be hazardous & should be used according to label directions & technical data information. Appropriate respiratory protection should be worn at all times while products are in use—read product label for specific details. Statements & methods described are based upon the latest standard of technology known to the manufacturer. Application procedures cited are suggestions only & are not to be interpreted as warranty for events resulting from their use.